Maryland Historical Trust

Maryland Inventory of Historic Properties number:	845	
Name: B-0033/WAZYGOZ RD.C	Worling FAUS.	
The bridge referenced herein was inventoried by the Maryland St Historic Bridge Inventory, and SHA provided the Trust with eligi The Trust accepted the Historic Bridge Inventory on April 3, 200 determination of eligibility.	ibility determinations in February 2001.	
MARYLAND HISTORICAL TRUST Eligibility Recommended Eligibility Not RecommendedX		
Criteria:ABCD Considerations:A _		
Comments:		
Reviewer, OPS:_Anne E. Bruder	Date:3 April 2001	

MHT No. <u>BA-2845</u>

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/ MARYLAND HISTORICAL TRUST

SHA Bridge No. B0033 Bridge name Walker Road over Little Falls
LOCATION: Street/Road name and number [facility carried] Walker Road
City/town Walker Vicinity X
County Baltimore
This bridge projects over: Road Railway Water X Land
Ownership: State County X Municipal Other
HISTORIC STATUS: Is the bridge located within a designated historic district? Yes NoX
Name of district
BRIDGE TYPE: Timber Bridge: Beam Bridge: Truss -Covered Trestle Timber-And-Concrete
Stone Arch Bridge
Metal Truss Bridge
Movable Bridge: Swing Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder : Rolled Girder: Rolled Girder Concrete Encased Plate Girder: Plate Girder Concrete Eucased
Metal Suspension
Metal Arch
Metal Cantilever
Concrete X : Concrete Arch Concrete Slab X Concrete Beam Rigid Frame Other Type Name

DESCRIPTION: Setting: Urban	Small town	Rural	X
Describe Setting:			

Bridge No. B0033 carries Walker Road over Little Falls in Baltimore County. At the bridge location, Walker Road runs north-south and Little Falls flows west to east. The bridge is located at a crossroads known as Walker, 61 meters (200 feet) south of Stabler Church Road, 30 meters (100 feet) north of the Gunpowder Falls State Park (NCRR Trail), and is surrounded by woodland and open space.

Describe Superstructure and Substructure:

Bridge No. B0033 is a 1-span, single-lane, concrete slab bridge. The bridge, built in 1915, has not been reconstructed or had any major rehabilitation. The total structure length is 13.1 meters (43 fcet), with a span length of 12.2 meters (40 feet) and has a clear roadway width of 5.3 meters (17.3 feet). The out-to-out width is 6.5 meters (21.3 feet); there are no sidewalks. The concrete slab is .45 meters (1.5 feet) thick, and it has a 7.62 centimeters (3 inch) thick bituminous wearing surface. The structure has solid panel concrete parapets, which are integral with the concrete slab, and the roadway approaches have metal guard rails on both sides of the bridge. The north approach roadway width is 5.5 meters (18 feet), while the south roadway approach is 4.3 meters (14 feet) wide. The south approach roadway has a moderate horizontal curve. The substructure consists of two concrete abutments. There are four U-shaped concrete wing walls. The bridge is posted for 13.6, 17.2 and 30.8 tonnes (15, 19 and 34 tons) for H15, MD Type 3 and MD Type 3S2 vehicles, respectively. The structure has a sufficiency rating of 81.7.

According to the 1997 bridge inspection report, this structure was in satisfactory condition with spalling and cracking. The approach roadways have minor settlement at the roadway-bridge transitions. Both approach roadway surfaces have moderate potholes, while the south approach pavement has a patch across the entire roadway at the bridge transition. The concrete deck has honeycombing, minor cracking and spalling of the soffitts. The integral parapets exhibit minor spalling with no structural defects. The concrete abutments have minor scaling and spalling, while the wing walls are in good condition with minor map cracking and scaling.

Discuss Major Alterations:

According to the 1997 bridge inspection report, the structure has not been altered.

WHY was the bridge built?

The bridge was constructed in response to the need for more efficient transportation network and increased load capacity.

WHO was the designer?
Unknown
WHO was the builder?
Unknown
WHY was the bridge altered?
N/A
Was this bridge built as part of an organized bridge-building campaign?
Unknown
SURVEYOR/HISTORIAN ANALYSIS:
This bridge may have National Register significance for its association with: A - Events B- Person C- Engineering/architectural character X
The bridge is eligible for the National Register of Historic Places under Criterion C, as a significant example of concrete slab construction. The structure has a high degree of integrity and retains such character-defining elements of the type as the slab, parapets, abutments and wing walls.

Was the bridge constructed in response to significant events in Maryland or local history?

Reinforced concrete slab bridges are a twentieth century structure type, easily adapted to the need for expedient engineering solutions. Reinforced concrete technology developed rapidly in the early twentieth century with early recognition of the potential for standardized design. The first U.S. attempt to standardize concrete design specifications came in 1903-1904 with the formation of the Joint Committee on Concrete and Reinforced Concrete of the American Society of Civil Engineers.

Maryland's roads and bridge improvement programs mirrored economic cycles. The first road improvement of the State Roads Commission was a 7 year program, starting with the Commissions establishment in 1908 and ending in 1915. Due to World War I, the period from 1916-1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920-1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund (with an equal sum from the counties) the building of lateral roads. the number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930. By 1930, Maryland's primary system had been inadequate to the huge freight trucks and volume of passenger cars in use, with major improvements occurring in the late 1930's. Most improvements to local roads waited until the years after World War I.

In the early years, there was a need to replace the numerous single lane timber bridges. Walter Wilson Crosby, Chief Engineer, stated in 1906, "the general plan has been to replace these [wood bridges] with pipe culverts or concrete bridges and thus forever do away with the further expense of the maintenance of expensive and dangerous wooden structures." Within a few years, readily constructed standardized bridges of concrete were being built throughout the state.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is located in an area which does not appear to be eligible for historic designation.

Is the bridge a significant example of its type?

The bridge is a potentially significant example of a concrete slab bridge, possessing a high degree of integrity.

Does the bridge retain integrity of important elements described in Context Addendum?

The bridge retains the character-defining elements of its type, as defined by the Statewide Historic Bridge Context, including the slab, parapets, abutments and wing walls.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?

This bridge is not a significant example of the work of a manufacturer, designer, and/or engineer.

Should the bridge be given further study before an evaluation of its significance is made?

No further study of this bridge is required to evaluate its significance.

BIBLIOGRAPHY:

Book Company, New York.

County inspection/bridge filesX Other (list):		SHA inspection/bridge files		
Ketch 1908	um, Milo S. The Design of Highway Bridges and the Calcu Engineering News Publishing Co., New York.	ulation of Stresses in Bridge	Trusses.	The
1920	The Design of Highway Bridges of Steel Timber of	and Concrete Second edition	McGraw	-Hil

Lay, Maxwell Gordon

Ways of the World: A History of the World's Roads and of the Vehicles That Used Them. Rutgers University Press, New Brunswick, New Jersey.

Maryland State Roads Commission

1930a Report of the State Roads Commission for the Years 1927, 1928, 1929 and 1930. State of Maryland, State Roads Commission, Baltimore.

1930b Standard Plans. State of Maryland, State Roads Commission, Baltimore.

Taylor, Frederick W., Sanford E. Thompson, and Edward Smulski


1939 Reinforced-Concrete Bridges with Formulas Applicable to Structural Steel and Concrete. John Wiley & Sons, Inc., New York.

Tyrrell, H. Grattan

1909 Concrete Bridges and Culverts for Both Railroads and Highways. The Myron C. Clark Publishing Company, Chicago and New York.

SURVEYOR:

Date bridge recorded	d <u>July 1998</u>	
Name of surveyor	Caroline Hall/Tim Tam	burrino .
Organization/Addres	ss P.A.C. Spero & Co.,	40 W. Chesapeake Avenue, Baltimore, MD 21204
Phone number(410)	•	FAX number (410) 296-1670





1. BA-2845 2. Walker Road over Little Falls

3. Baltmore Co., MD

4. Wallace, Montgomery & Assoc.

5. 12/97

6, MD SHPO

7. Elevation looking upstream

8, 10F4



1. BA-2845
2. Walker Road over Little Falls
3. Baltimore Co., MD
4. Wallace Manda 14.

4. Wallace, Montgomery & Assoc. 5. 12/97

6. MD SHPO

7 Elevation looking downstream 8. 2 of 4

9,



- 1. BA-2845
- 2. Walker Road over Little Falls
- 3. Baltimore Co., MD
- 4. Wallace, Montgomery & Assoc,
- 5. 12/97
- 6, MD SHPO
- 7. Looking Northeast
- 8. 3 of 4



1. BA-2845

- 2. Walker Road over Little Falls
- 3. Baltimore Co., MD
- 4. Wallace, Montgomery & Assoc.
- 5, 12/97
- 6. MD 54PO
- 7. Looking Southwest
- 8, 4 of 4